

FIG.2




FIG.3


553

FIG.4




FIG.5

700

SCREEN

PRINT PROCESSING TIME ANALYSIS RESULT

?

X

CURRENT PRINT PROCESSING TIME DATA

PRINTER NAME : XXX PM—xxx

OUTPUT PORT : XXX. XXX (LPR PORT)

FILE NAME : XXX

STATUS : PRINTING

1) PRINTER MAXIMUM PROCESSING TIME : 370kbyte/sec

2) PRINTER CURRENT PROCESSING TIME : 100kbyte/sec

3) OUTPUT PORT DATA TRANSFER RATE : 100kbyte/sec

4) PRINTER DRIVER DATA GENERATION : 340kbyte/sec

PROCESSING TIME

PRINT PROCESSING TIME ANALYSIS RESULT

" DUE TO A LOW DATA TRANSFER RATE, DATA PROCESSING TIME OF THE PRINTER AND DATA GENERATING ABILITY OF THE COMPUTER ARE NOT EFFICIENTLY USED.

THE CURRENTLY USED PORT IS XXX.XXX (LPR PORT), AND BY REPLACING WITH XXX/XX PORT, THE PRINT PROCESSING TIME CAN BE IMPROVED.

CLOSE